



SINO GOOKII TECH CO.,LTD.

REWINDER PACKING LIST

Note: Please handle with care after receiving our products. After opening the package, check all accessories of the product and confirm whether they are complete according to the following list. Usually we will send some extra small parts in case of loss or shortage.

	
Column*4 (L1, L2, L3, L4)	Short Crossbar*4 (H1, H2, H3, H4)
	
Long Crossbar*5 (C1D, C2D, C3D, C4S, C5S)	Shaft*5 pcs
	
Bearing Block*10 pcs, Bolt*20 pcs	Meter Counter *1 set



SINO GOOKII TECH CO.,LTD.



Connector*36 pcs, Bolt*80 pcs



Corn Tip*4 pcs



Fixing Ring*10 pcs



Hand Wheel*1 set



Rubber Pad *4 pcs



Protective Cover*4 pcs



Wrench*2 pcs



SINO GOOKII TECH CO.,LTD.

INSTALLATION INSTRUCTIONS


Step 1: Find 4 columns (L1, L2, L3, L4, L=72cm) and install the rubber pads.



Step 2: Find 4 crossbars (H1, H2, H3, H4, L=52CM).



Step 3: Assemble the crossbar and column into two groups as shown in the figure below, one on the left and one on the right. A total of 12 connectors and 24 bolts are used.



Step 4: Install cross bars C4S and C5S with a length of 128CM as shown in the figure below. A total of 8 connectors and 16 bolts are used.



SINO GOOKII TECH CO.,LTD.



Step 5: Install cross bars C1D and C2D with a length of 120CM as shown in the figure below. A total of 12 connectors and 24 bolts are used.



Step 6: Install cross bar C3Z with a length of 120cm as shown in the figure. The position can be adjusted according to the actual situation. A total of 12 connector and 24 bolt are used.




SINO GOOKII TECH CO.,LTD.



Step 7: Install the protective cover of the crossbar as shown in the figure (Upper, Front right and left corners, back right and left corners) .




Step 8: Install 5 sets of bearing seats and shafts as shown in the figure. The longest shaft is installed in the uppermost position. The projecting end of the bearing is installed outward, after installing the shaft, tighten the locking screw.






SINO GOOKII TECH CO.,LTD.

Step 9: Install the cone tips on the upper and front shafts.



Step 10: Two fixing rings shall be installed on each other shafts (three shafts without the corn tips), and the length of the middle interval shall be consistent with the width of the rolling material.



Step 11: Install the meter counter in the cross bar C3Z as shown in the figure below. Adjust the position of the meter counter to assure the meter counter and the shaft is slightly contacted.



Step 12: Install the hand wheel on the uppermost shaft right end.



The above is the installation instructions of our rewinder machine. Thank you for choosing GookiiTech  products, please feel free to contact us if you have any questions.